

Release Notes for software update v1.13 for AMTRON® charge controller HCC3

Release Notes for Software update v1.13_10141

Functional changes

- Enabling the 'Modbus TCP Server' function
- Updating the firmware of the WLAN module WGM110 from v1.1.7 to v1.1.9
 - Resolving problems when connecting to the AMTRON[®] access point ('password invalid')

Errors and troubleshooting:

- Improved stability when operating with the WGM110 WLAN module in 'access point' mode
- Improved stability when operating with the WGM110 WLAN module in 'client' mode
- Performance improvement when operating with WLAN module WGM110 in 'Client' mode
- Faster re-connection to a WLAN access point with the WLAN module WGM110
- Optimized behavior when operating in a network with WLAN repeaters
- Increased reliability when performing a software update
- Improved stability in the wired network (Ethernet)
- Additional status messages in the service interface
- Improved stability during operation with the SMA Sunny Home Manager